

RISK MANAGEMENT REPORT

TYPE	Excavator - Small (0 - 9.9 Tonne)
MAKE	Kubota
MODEL	U55-4G
SERIAL NUMBER	27111
ENGINE NUMBER	8RN7232



Report Number	AHS 20250314-1436
Date	14-Mar-2025
Created By	Alvaro Benitez
Assessor	Alvaro Benitez
Assist. Assessor(s)	
Completed By	Alvaro Benitez
Owner	Australian Hammer Supplies Pty Ltd
Assessment Purpose	Sale
State	NSW

TABLE OF CONTENTS

		\sim	\sim		- 4
	_	- 1	 റ	NI	7
•	_		 L J	IV	

IMPORTANT INFORMATION

Contains information outlining the scope and any limitations applicable to this Risk Management Report

SECTION 2

MACHINE DETAILS

Contains standard machine specifications and details of any extras fitted

SECTION 3

RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT

Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5

SECTION 4

RISK TREATMENTS REQUIRED

Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references

SECTION 5

RISK TREATMENTS IN PLACE

Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references

SECTION 6

IMAGES AND NOTES

Contains images & any relevant information entered by the assessor





SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Friday, 14 Mar 2025 2:47 PM

This Risk Management Report has been prepared for -

(insert recipient name/company name)

This document has been prepared to cover the sale or transfer of this item of plant between the Company identified on the front cover and their named recipient. This report must not be used for any subsequent sale or transfer.

This document is provided to meet duty of care obligations as set out in relevant state and territory health and safety regulations for the supply of plant and the sale and transfer of plant.

The safety hazards associated with the operating and maintaining of this item of plant have been identified as far as practical by visual inspection. This item of plant is being sold in an "as-is" condition with known and unknown safety hazards. No physical testing has been conducted (eg. Wire rope tests, stress tests, structural/non-destructive tests, noise tests, vibration tests, brake tests, insulation tests etc.) unless stated otherwise in the notes.

This document is not intended to provide information on, nor warrant the mechanical, electrical or structural condition of this item of plant. Any information on standard features have been supplied through the manufacturer and should be used as a guide only until otherwise verified.

This item of plant should be further assessed, tested and inspected or dismantled as necessary to gauge any further hazards and /or risks relating to SPECIFIC WORKPLACE USE, which are currently unknown, in accordance with relevant standards, regulations and acts.

Under common law and relevant state and territory health and safety acts, regulations and codes of practice, there is a requirement for the plant owner, employer and operator to exercise a duty of care in the safe operation and maintenance of plant. Accordingly before this item of plant is supplied to, or used at any workplace it must be inspected to ensure it is in a fully operational, safe and serviceable condition and that operators and maintenance personnel are appropriately trained in the use & maintenance of this item of plant.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

40		Manufacturers specified noise level dBA	
၂ လ		2. Ambient noise level dBA	
l ₹		3. Noise level - Operator position (high idle) dBA	
	- NOISE TEST RESULTS	4. Noise level - Operator position (low idle) dBA	
IШ	- NOISE TEST RESULTS	5. Noise level LHS dBA @ m (high idle)	
		6. Noise level Front dBA @ m (high idle)	
╽╝		7. Noise level RHS dBA @ m (high idle)	
=		8. Noise level Rear dBA @ m (high idle)	
MACHIN	BUCKET	Standard bucket capacity, SAE rated (m3)	
	BUCKET	Standard bucket width (mm)	
🗟	CAPACITIES	Fuel Tank Capacity (Litres)	
l –		Hydraulic Oil Tank Capacity (Litres)	
		Dig depth to cut 2.44 m level bottom (mm)	
		Digging depth (mm)	
		Dump height (mm)	
	DIMENSIONS/WEIGHTS	Ground clearance (mm)	
		Max depth of vertical wall (mm)	
		Maximum Reach Height (mm)	
		Operating weight (kg)	





Kubota U55-4G

Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By

Alvaro Benitez 14-Mar-2025

	Tailswing radius (mm)
	Transport Height (mm)
	Transport Length (mm)
	Width (mm)
	Engine Displacement (Litres)
	Engine Hours
ENGINE	Engine Make & Model
ENGINE	Engine Number
	Engine Power (kW@rpm)
	Number of Cylinders
EXTRAS	Spare spool for attachments? Yes/No
	Quick Hitch Make
НІТСН	Quick Hitch Model
	Quick Hitch Serial No.
	Flow of main pumps (L/Min)
HYDRAULICS	Pump Types
	Relief valve pressure, main pumps (Bar)
DI ANT CLASSIFICATIONS	Class
PLANT CLASSIFICATIONS	Year
	FOPS Compliance No.
SAFETY STRUCTURES	FOPS Serial No.
SAFETT STRUCTURES	ROPS Compliance No.
	ROPS Serial No.
TRACKS	Track length on ground (mm)
IRACKS	Track pad width (mm)
TRANSMISSION	Speed (km/h)
	Arm breakout (kgf)
WORK CAPABILITIES	Bucket breakout (kgf)
WORK CAPABILITIES	Gradeability - Degrees/(%)
	Reach @ ground level (mm)





SECTION 3 RISK ANALYSIS / RISK EVALUATION

RI:	SK ANALYSIS					
Ĭ.◀	← CONSEQUENCE ←					
LIKELIHOOD		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia
LIKELI	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25
↓	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15

LUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.		
RISK EVA	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.			
		Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within one month.		
		Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented within three months.		

TREATMENT		st appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits ard to legal, regulatory and other requirements. (source AS/NZS ISO 31000:2018)
REAT	Eliminate	Eliminate the risk source.
RISK T	Substitute	Provide an alternative that is capable of performing the same task which is safer.
_	Isolate	Isolate people from the hazard.
	Engineering	Provide or construct a physical barrier or guard.
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.





SECTION 4 RISK TREATMENTS REQUIRED

This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 - Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.

HAZARD(S)	Prelim. Risk	Residual Risk	Time	Duo Data	Date	Initial
HAZARD(3)	Rating	Rating	Frame	Due Date	Due Date Rectified	initiai

SECTION 5 RISK TREATMENTS IN PLACE

This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.

		HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating			
ELIVERY	Ш	CRUSHING	HIGH 22	MEDIUM 15			
DELIV		nents in Place: SWMS Loading/Unloading all operators follow approved SWMS/SOP when loading and unloading this made	hine to and from a flat top tru	ck or trailer, low loader or			
	References	S: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations				
		CRUSHING	HIGH 22	MEDIUM 15			
	Ensure that a	nents in Place: SWMS Load Restraint all operators follow the approved SWMS/SOP when restraining this machine for	•				
	References	S: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act	& Regulations				
NOL	NOMINATED OPERATOR ONLY	INCORRECT OPERATION	CRITICAL 24	MEDIUM 15			
OPERATION	Only persons competent/lid operate this i	nents in Place: Operator Competency s who are qualified, trained and experienced and/or hold the relevant certification censed person available for operation of this item of plant then only persons who tem of plant. S: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act &	o are supervised by a compet	•			
	\triangle	CRUSHING	CRITICAL 24	MEDIUM 15			
		nents in Place: Quick Hitch Movement blant is fitted with a quick hitch which will not allow unintended movement of the s: AS13031	attachment if the primary rete	ention system fails.			
	\Box	INCORRECT OPERATION	HIGH 22	MEDIUM 15			
	Risk Treatments in Place: Operation Handbook The manufacturer's operation handbook has been supplied for this item of plant.						
	This handbook must be available at all times to all potential operators and supervisory staff. All potential operators must read and be familiar with this handbook prior to operating.						
		isk assessment/Job Safety Analysis must be undertaken covering all operating s should be produced for specific tasks associated with use of this item of plant.	processes and environments	associated with this item of			
	References: Work Health & Safety Act & Regulations- , Occupational Health & Safety Act & Regulations						







Risk Treatments in Place: Quick Hitch Operation Handbook

The manufacturer's operation handbook has been supplied for this quick hitch.

This handbook must be available at all times to all potential operators and supervisory staff. All potential operators must read and be familiar with this handbook prior to operating.

A complete risk assessment/Job Safety Analysis must be undertaken covering all operating processes and environments associated with this quick hitch. SWMS should be produced for specific tasks associated with use of this quick hitch.


References: AS13031

INCORRECT OPERATION HIGH 22 MEDIUM 15

Risk Treatments in Place: Pre-op Checklist Excavator

A pre-operation checklist is available for this Excavator. This checklist must be completed by all operators prior to operating this Excavator.

References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act & Regulations



Risk Treatments in Place: SOP Excavator

Safe Operation Procedures are available for this Excavator. The information in the Safe Operation Procedures must be followed at all times whilst operating this Excavator.

References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act & Regulations



INCORRECT OPERATION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Control Labels

All controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their purpose and method of operation. These labels must be maintained in a clean and serviceable condition at all times.

References: AS/NZS4024.1905



CRUSHING, FALLING

HIGH 22

MEDIUM 15

Risk Treatments in Place: Passenger Seat Label

This item of plant is fitted with a clear hazard warning label re: Operator only, No passengers. Passengers must not be carried at anytime. This label must be clear and legible at all times whilst this item of plant is in operation.

Legislation: State Health & Safety Legislation & Regulation

References: AS1319-



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: ROPS Label

The warning label stating that the ROPS must not be damaged at any time (including cuts, drill holes and welds) must be present, clean and legible at all times.

References: ISO3471



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: ROPS seat belt label

This item of plant is fitted with a ROPS and has an advisory label stating that "seatbelts must be worn".

This label must be present, clean and legible at all times.

All operators and passengers must wear seatbelts whilst on this item of plant.

References: AS2294, ISO3471





	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
747	ELECTROCUTION	HIGH 22	MEDIUM 15

Risk Treatments in Place: Electrical Approach Distances

This item of plant has a hazard warning label re: overhead electrical hazards and minimum approach distances fitted. These distances must be adhered to strictly. These labels and tables must be present, clear and legible at all times.

Spotters are required when working within 5 metres of the minimum approach distance of any live electrical apparatus.

Any encroach within the minimum approach distances must only occur if the following provisions have been met -

- 1. The machine is designed to work within the minimum approach distances
- 2. Permission has been granted by the electricity company and
- 3. Safe systems of work have been documented and approved.

References: ISO31000



ELECTROCUTION, EXPLOSION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Before You Dig (AUS)

This item of plant is fitted with a clear hazard warning label re: underground services and advice "Before You Dig, visit www.byda.com.au" to the operator work area. This advice must be adhered to strictly. Digging into an electricity cable or gas pipe can cause serious injury or death. Damaging a pipe or cable may also lead to isolating a community from emergency services such as fire, police or ambulance. This label must be present, clear and legible at all times.

References: ISO31000



COLLISION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Phone Use label

This item of plant is fitted with an instruction label advising that mobile phones must not be used whilst operating this machine. Accordingly all operators must not use a mobile phone at any time whilst operating machine. If phone use is necessary then operator must place machine in park configuration in a safe position prior to phone use. Operators MUST adhere to this advice at all times.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: AS1319-, ISO31000



POISONING, EXPLOSION, BURNS

HIGH 22

MEDIUM 15

Risk Treatments in Place: Tank ID Label

The tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if appropriate any necessary controls re: the contents. These must be present, clear and legible at all times. (this includes radiator, hydraulic, water and petrol/diesel tanks etc.)

References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act & Regulations



FIRE

HIGH 21

MEDIUM 15

Risk Treatments in Place: Fire Extinguisher

This item of plant is fitted with an approved and maintained fire extinguisher. Fire extinguisher(s) must be present and fully functional at all times. They must be readily accessible to the operator. Regular inspections must also be carried out in accordance with the manufacturer's requirements and AS 1851 – 1995

References: AS10896.1, AS1851



INSTABILITY, CRUSHING

HIGH 21

MEDIUM 15

Risk Treatments in Place: Boom Rated Capacity Label

This item of plant has a rated capacity label fitted to each side of the boom. Ensure that these labels are clear and legible at all times whilst this item of plant is in operation. Operators must not exceed this rated capacity at any time during operation.

References: AS1418.8





Make Kubota Model U55-4G

ype Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date 27111 Alvaro Benitez 14-Mar-2025

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
CRUSHING, INCORRECT OPERATION	HIGH 21	MEDIUM 15

Risk Treatments in Place: Quick Hitch Information

This hydraulic quick hitch has the following information marked upon it -

- 1. The manufacturer's name and address
- 2 Model
- 3. Serial number
- 4. The year of manufacture
- 5. The mass of the hitch in kilograms
- 6. The lift point capacity (if fitted) in kilograms

This information must be considered by all operators when assessing the suitability of the hitch for any task. Failure to consider and or comply with this information could lead to serious injury or death.

References: AS13031



CRUSHING, PINCHING

HIGH 21

MEDIUM 15

Risk Treatments in Place: Swing Boom Crush Label

This item of plant has clear hazard warning labels re: pinch point/crush zone, keep clear, that are attached to each side of the boom swing/pivot point. These must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201, AS1319-



HEARING LOSS

HIGH 19

MEDIUM 14

Risk Treatments in Place: Hearing Protection Label - Operator

The hazard warning label(s) re: wearing of hearing protection attached to this item of plant refer to the level of noise produced. Permanent hearing damage will result if hearing protection is not worn. These labels must be present, clear and legible at all times whilst this item of plant is in operation.

References: AS3781-, AS/NZS1269



CRUSHING, STRIKING, COLLISION

HIGH 19

MEDIUM 14

Risk Treatments in Place: Tail Swing Label

The rear of this item of plant has a hazard warning label re: general plant movement, tail swing, keep clear. It must be present and fully functional and serviceable at all times.

References: ISO20474-



CRUSHING

MEDIUM 14

MEDIUM 13

Risk Treatments in Place: Front Grader Blade Label

The front blade on this item of plant is fitted with a hazard warning label re: crush zone, keep clear. This label must be present and fully functional and serviceable at all times.

References: AS1319-, ISO20474-



ENTANGLEMENT, SHEARING, BURNS

MEDIUM 14

MEDIUM 13

Risk Treatments in Place: Engine Guard Label

The engine fan and alternator belts, pulleys and gears are guarded. These guards have clear legible hazard warning labels re do not open or remove guards while engine is running. These labels must be present, legible and easily seen at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201, AS1319-



CRUSHING, COLLISION

MEDIUM 12

LOW 6

Risk Treatments in Place: Warning Device (horn)

This item of plant is fitted with a fully functional audible warning device such as a horn. This must be easily accessed by the operator, and easily identifiable by nearby pedestrians.

All operators should ensure the warning devices are functional at the start of each shift, by completing pre-start checklists. Warning devices should operate automatically where appropriate (eg reversing)

References: ISO7731, ISO9533





Make Kubota Model U55-4G

Type Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By

27111 Alvaro Benitez 14-Mar-2025

Page 8 of 15

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
COLLISION	MEDIUM 9	LOW 5

Risk Treatments in Place: Recovery Point Label

This item of plant is fitted with a hazard warning label adjacent the recovery tow point which states "Recovery tow point – Read manufacturer's towing instructions before towing". Failure to do so could result in DEATH or SERIOUS INJURY.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000



CRUSHING

CRITICAL 24

MEDIUM 15

Risk Treatments in Place: Fully Automatic Quick Hitch

This item of plant is fitted with a fully automatic quick hitch.

References: AS13031



CRUSHING

CRITICAL 24

MEDIUM 15

Risk Treatments in Place: Automatic(Quick) Hitch

This item of plant is fitted with a quick hitch that is fitted with a primary retention device and safety system that meet the following requirements -

- 1. Must be intentionally disengaged to remove attachments
- 2. The safety system is automatically activated as part of the engagement process
- 3. Has means of verifying engagement of both the primary retention device and the safety system from the operator position.

These requirements must be met at all times whilst this item of plant is in operation.

References: AS13031



STRIKING, BURNS

HIGH 22

MEDIUM 15

Risk Treatments in Place: Hydraulic Hoses

This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear, immediate action must be taken to control the risk arising from this wear. These inspections must be documented.

Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks. Always wear appropriate gloves when handling hydraulic hoses.

Hydraulic pressure can be stored and is a hazard. Always connect and disconnect hydraulic hoses as per the manufacturer's manual.

References: AS4024, AS2671



CRUSHING, COLLISION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Loose Items - Operator Work Area

All items that could cause harm to the operator in the event of a collision or rollover are securely restrained.

References: ISO31000



CRUSHING, NON COMPLIANCE

HIGH 22

MEDIUM 15

Risk Treatments in Place: Control Lock out

The primary operator controls are fitted with an isolation device which meets the following requirements -

- a) Must be engaged to allow entry & exit of the machine
- b) Is not easily bypassed.

This device deactivates the primary operator controls. This must be employed during entry, exit and while performing maintenance on this item of plant.

This device must be fully functional at all times whilst this item of plant is in operation.

References: ISO10968








CRUSHING HIGH 22 MEDIUM 15

Risk Treatments in Place: Seat Belt

This item of plant is fitted with an operator seat belt. This seat belt must be free from damage, and permanently and sturdily attached at all times whilst this item of plant is in operation. Operators must use this seat belt at all times during operation.

References: ISO6683

References: AS4024.1603



Risk Treatments in Place: Movement Awareness Alarm

An automatic movement awareness alarm is fitted to this item of plant. This alarm is automatically activated when travel in any direction occurs. It must be fully functional and serviceable at all times whilst this item of plant is in operation.


References: ISO7731, ISO9533



Risk Treatments in Place: Quick Hitch Controls

The quick hitch operation control is fitted with a device/method to prevent accidental operation. This device must be fully functional at all times whilst this item of plant is in operation.

References: AS13031



Risk Treatments in Place: Hydraulic Hose Failure Shield

This item of plant is fitted with a sturdy, permanent shield(s) between the hydraulic hoses and any body parts of the operator to provide protection during a hose or component failure. This shield(s) must be present and fully functional at all times whilst this item of plant is in operation.

References: AS4024, ISO4413, AS2671



Risk Treatments in Place: Quick Hitch Operation Alarm

This item of plant is fitted with a quick hitch with a fully functional audible alarm fitted to the operator work area to alert the operator that the host machine is in the mode that allows for the controls to be operated to engage or disengage attachments.

This alarm must be fully functional at all times whilst this item of plant is in operation.


References: AS13031



Risk Treatments in Place: Safe Operator Location

This machine is designed so that the operator is isolated from all danger zones whilst at the operator position. This condition must exist at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



Risk Treatments in Place: Machine Lights

This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light.

References: ISO20474-





Make Kubota Model U55-4G

Type Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date 27111 Alvaro Benitez 14-Mar-2025 MEDIUM 15

MEDIUM 15

HAZARD(S) Prelim. Risk Rating **Residual Risk Rating ENTANGLEMENT** HIGH 22 MFDIUM 15

Risk Treatments in Place: Engine Guards

The engine fan and alternator belts, pulleys and gears are guarded. These guards must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1601



COLLISION

HIGH 22

MEDIUM 15

Risk Treatments in Place: Beacon

This item of plant is fitted with a safety beacon. This beacon must meet the following criteria at all times whilst this item of plant fitted is in operation -

- Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant structure whilst the plant is in operation)
- Is fitted in the most appropriate location on machine to maximise visibility without risking continual damage

NOTE: more than one beacon may be fitted to meet these criteria.

References: ISO20474-



OPERATIONAL MALFUNCTION

HIGH 22

I OW 2

Risk Treatments in Place: Plant Modification

The plant is in original condition.

References: ISO31000



ENTRAPMENT

HIGH 21

MEDIUM 15

Risk Treatments in Place: Two Operator Exits

The operator cabin/work area on this item of plant has a minimum of two (2) possible exits. These must be functional and accessible at all times whenever the item of plant is manned, whether during operation or maintenance activities.

References: AS5327



ENTRAPMENT

HIGH 21

MEDIUM 15

Risk Treatments in Place: Emergency Exits

The emergency exits for this item of plant meet the following requirements -

- 1. Clearly and legibly labelled
- 2. Instructions for use are clear and legible and located adjacent the exit
- 3. Any required tools required for use are available e.g. Emergency hammers

These exits must be legibly labelled and fully functional at all times whenever the item of plant is manned, whether during operation or maintenance activities.

References: ISO31000



POOR VISIBILITY, COLLISION

HIGH 21

MEDIUM 15

Risk Treatments in Place: Windscreen Wipers

The windscreen wipers and washers fitted to this item of plant must be fully functional at all times.

References: AS/NZS4024.1201

ROPS FITTED

CRUSHING

HIGH 21

MEDIUM 15

Risk Treatments in Place: ROPS

A Roll Over Protective Structure (ROPS) to ISO 3471, ISO 12117.1 or 2, AS 2294 or AS 4987 is fitted to this item of plant. A permanent label stating this standard must be attached to the structure at all times. This structure provides a safety envelope during a rollover. A warning label re: wearing of seat belts at all times whilst this item of plant is in operation and accordingly seat belts must be worn at all times during operation.

References: AS4987, AS2294, ISO3471





Make Kubota Model U55-4G

Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date

Alvaro Benitez 14-Mar-2025

Page 11 of 15

	HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
A	CRUSHING	HIGH 21	LOW 5

Risk Treatments in Place: FOPS General

This item of plant is fitted with a Level I Falling Objects Protective Structure (FOPS). This structure is designed to protect the operator from small falling objects (e.g. bricks, small concrete blocks, hand tools)

Before operating this item of plant a task based risk assessment must be conducted to determine the level of FOPS required.

Level I - withstands 1,365 joules (e.g. 20kgs @ 7m drop, 70kgs @ 2m drop)

- operations such as highway maintenance, landscaping and other construction site services

Level II - withstands 11,600 joules (e.g. 200kgs @ 6m drop, 394kgs @ 3m drop)

- operations such as site clearing, overhead demolition or forestry

This task risk assessment must be undertaken before each operation, in particular when the item of plant is moved to a new location, even if it is within the same site.

References: ISO10262



INCORRECT OPERATION

HIGH 20

MEDIUM 14

Risk Treatments in Place: Intuitive Controls

The controls fitted to this item of plant are orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left. This design feature must be maintained at all times whilst this item of plant is in operation.

References: AS/NZS4024.1906



STRAINS

HIGH 19

LOW 5

Risk Treatments in Place: Controls Ergonomics

All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution.

References: AS/NZS4024.1901



INCORRECT OPERATION, SLIPPING

HIGH 17

LOW 6

Risk Treatments in Place: Control Levers/Pedals/Buttons

All controls including all levers, buttons, pedals, switches etc. must be kept non-slip and free from damage at all times.

References: AS/NZS4024.1901



SLIPPING

MEDIUM 12

LOW 6

Risk Treatments in Place: Operator Work Area Access/Egress

Safe access and egress to the cabin/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.

All personnel must -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Never carry an object(s) in his/her hand(s) during access and egress.
- 4. Never jump off machine.

References: AS5327



FALLING, SLIPPING

MEDIUM 12

LOW 6

Risk Treatments in Place: Access/Egress Instruction Label

An instruction label is fitted adjacent access/egress areas to advise all personnel of the following -

- 1. Always face the item of plant during access and egress.
- 2. Always maintain three points of contact during access and egress.
- 3. Ensure the steps are clean.
- 4. Never jump off machine.

This label must be clear and legible at all times whilst this item of plant is in operation.

References: ISO31000





Make Kubota Model U55-4G

Type Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By 27111 Alvaro Benitez 14-Mar-2025

Page 12 of 15

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	
If your car't see my mirrors I CAN'T SEE YOU. POOR VISIBILITY, COLLISION	MEDIUM 12	MEDIUM 11	

Risk Treatments in Place: Operator Mirror

This item of plant is fitted with at least one rear vision mirror. This mirror must be fully functional and clean at all times whislt this item of plant is in operation.

References: ISO5006

BATTERY COVER

ELECTRIC SHOCK, BURNS

MEDIUM 12

LOW 6

Risk Treatments in Place: Battery Cover

All batteries fitted to this item of plant are constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation. The constraint and cover must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



INCORRECT OPERATION, SLIPPING

MEDIUM 9

LOW 4

Risk Treatments in Place: Work Area Floors

All work area floors are non-slip and free from damage & debris.

Floor area must remain non-slip and free from damage & debris, including rubbish, tools and other items, at all times whilst this item of plant is in use.

References: AS/NZS4024.1201, ISO20474-



NON COMPLIANCE, STRAINS

MEDIUM 9

LOW 1

Risk Treatments in Place: Operator Seat

The operator seat fitted to this item of plant must remain free from damage and tears, and be permanently and securely fitted at all times.

References: AS/NZS4024.1401, ISO20474-



HEAT STROKE, DEHYDRATION

MEDIUM 9

LOW 4

Risk Treatments in Place: Air Conditioning

This item of plant is fitted with an air conditioned cabin. This air conditioned cabin helps control the air quality and temperature for the operator and also provides shade from the sun. The air conditioner must be fully functional and serviceable at all times whilst this item of plant is in operation.

References: ISO31000



BURNS

MEDIUM 9

LOW 5

Risk Treatments in Place: Exhaust

The engine exhaust on this item of plant is fitted with a guard to prevent injury to any person and control the risk of initiating a fire. It must be present and fully functional and serviceable at all times whilst this item of plant is in operation.

References: AS/NZS4024.1201



CURRENT OR PREVIOUS STRUCTURAL DAMAGE

CRITICAL 25

MEDIUM 15

Risk Treatments in Place: Structural Integrity

Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.

References: ISO31000





Serial Number Assessed By Date 27111 Alvaro Benitez 14-Mar-2025

HAZARD(S) Prelim. Risk Rating Residual Risk Rating HIGH 22 MEDIUM 15

Risk Treatments in Place: Maintenance Manual

The manufacturer's maintenance manual(s) has been supplied for this item of plant

These manual(s) must be available at all times to all users and maintenance staff of this item of plant. All users and maintenance staff must read and be familiar with these handbook(s) prior to maintaining or repairing this item of plant.

A complete risk assessment/JSEA must be undertaken covering all inspection, maintenance, servicing and transportation requirements of this piece of plant prior to use.

A full assessment of the competence of people using the book(s) must also be undertaken

References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act & Regulations



STRIKING, BURNS

HIGH 22

MEDIUM 15

Risk Treatments in Place: Hydraulic Damage

The hydraulic hoses to this item of plant are free from damage and protected against damage arising from contact with the plant structure. Ensure that hoses are free from damage and that protection is in place at all times whilst this item of plant is in operation. Inspection of the hydraulic hoses and protection system should be conducted regularly and documented as part of your plant safety programme.

References: AS4024, ISO4413, AS2671



CRUSHING

HIGH 22

MEDIUM 15

Risk Treatments in Place: ROPS Damage

The Roll Over Protective Structure (ROPS) fitted to this item of plant must remain free from damage at all times whilst this item of plant is in operation.

References: AS2294, ISO3471



OPERATIONAL MALFUNCTION

HIGH 22

LOW 2

Risk Treatments in Place: Major Fluid Leaks

This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmission, cooling system, air, fuel, drive line, wheel hubs, steering and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. Minor leaks detected must be repaired within 1-14 days.

References: ISO31000



OPERATIONAL MALFUNCTION

HIGH 21

MEDIUM 15

Risk Treatments in Place: Service Records

Service and maintenance records are available for this item of plant.

These records must continue to be managed and available at all times as part of your service and maintenance programme. (This programme includes the undertaking of regular inspections of the item of plant with specific reference to all OEM prescribed, scheduled and non scheduled service and maintenance requirements).

References: Work Health & Safety Act & Regulations-, Occupational Health & Safety Act & Regulations



POOR VISIBILITY, COLLISION

HIGH 21

MEDIUM 15

Risk Treatments in Place: Windows & Screens

Ensure the cabin/work area safety glass windows and screens are kept clean and free from cracks and other damage at all times whilst this item of plant is in use.

References: AS/NZS4024.1201, ISO20474-



INSTABILITY

MEDIUM 9

LOW 4

Risk Treatments in Place: Tracks

The tracks and track components must be inspected as part of a "pre start" checklist. These inspections must be documented as part of your plant safety programme.

References: ISO20474-





Make Kubota Model U55-4G

Type Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date 27111 Alvaro Benitez 14-Mar-2025

Page 14 of 15

SECTION 6 IMAGES AND NOTES

IMAGES

- No Images Available -

NOTES

- No Notes Available -





Make Kubota Model U55-4G

Type Excavator - Small (0 - 9.9 Tonne)

Serial Number Assessed By Date 27111 Alvaro Benitez 14-Mar-2025

Page 15 of 15



RISK MANAGEMENT REPORT

TYPE	Excavator - Small (0 - 9.9 Tonne)	Report Number	AHS 20250314-1436
MAKE	Kubota	Date	14-Mar-2025
MODEL	U55-4G	Created By	Alvaro Benitez
SERIAL NUMBER	27111	Assessor	Alvaro Benitez
ENGINE NUMBER	8RN7232	Assist. Assessor(s)	
		Owner	Australian Hammer Supplies Pty Ltd
		Assessment Purpose	Sale
		State	NSW

PURCHASER ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have recieved a copy of this risk management report. I also acknowledge that I am authorised to sign on behalf of the purchaser.

Name	
Company Name	
Position	
Signature	
Date	
The manufacturer's operational & maintenance handbooks have been supplied, (circle one) YES NO (initial) Please transfer this assessment to my Plant Assessor membership as a (circle one) HIRE / PLANT IN USE assessment. My Plant Assessor email is	



AHS 20250314-1436