


COMEUP

CRH-0710 CRANE

- Rated load: 230 KG
- Don't overload, Don't transport people



- I. Fasten safety sheet④ on the arm① with a screw.
- II. Fasten arm① and bracket② with a screw.
- III. Fix holder③ on the steel pipe or scaffold.
- IV. Put arm① and bracket② into the hole of holder③, then insert a R-pin.
- V. Hang winch on the arm① and fasten the screw⑥.