# **Instruction Manual**

**SKATES** 



**NOte:** Owner/Operator must read and under stand this instruction manual before using the skactes.

### Contents

1.GENERAL DESCRIPTION

2.FEATURES

3.USES

**4.EXPLODED FIGURES & PARTS LISTS** 

#### I GENERAL DESCRIPTION

Skates are ideal for all kinds of heavy equipment moving machinery installation and maintenance or heavy equipment moving machinery installation and maintenance or heavy a surgicional maximum and maintenance or heavy as a surgicional maximum and maximum and maintenance or heavy as a surgicional maximum and ma

#### 2 FEATURE

- 2.1 Low height transport safety(7-20cm)
- 2 % West pulling transport easily (about 8% of overall load mitteel position)
  - Combine easily strong adaptation (Kart 1 Co.)
    - 2.4 Small equipment, easy stolage

#### SERU C

- 3.1 Capacities at St 10, 8F20, SF25, SF30 and SF30 are respective 1T 2T, 2.5T, 3T, and 6T. Line pull roller in smable for pulling in straight line lastion and furning.
- 3.2 Capacities of SE102 and SE10 pareful 17 They are respectively will two and four scentro wheels and self-three for furned pulling.
- 1.3 CM50, CM 120 and CM240 are committation, capacities of which are respectively 51, 121 and 241. They are sulfable for pulling large mosts.
- 3.4 ST30. ST60 and 37120 participate of golding collers. Their department are respectively 31, or and 121. They can be pulled to change direction.

# THANK YOU FOR CHCOSING OUR SKATES. FOR YOUR SAFETY AND CORRECT OPERATION, PLEASE CAREFULLY READ THE MANUAL BEFORE USE.

**NOTE:** All of the information reported herein is based on data available at the time of printing. The factory reserves the right to modity its own products at any time without notice or incurring in any sanction. Please verifty with the factory for possible updates.

#### 1. GENERAL DESCRIPTION

Skates are ideal for all kinds of heavy equipment moving, machinery installation and maintenance.

#### 2. FEATURE

- 2.1 Low height, transport safety(7~20cm)
- 2.2. Weak pulling, transport easily (about 3% of overall load in ideal position)
- 2.3 Combine easily ,strong adaptation (load 1~60T)
- 2.4 Small equipment, easy storage


### 3. USES

- 3.1 Capacities of SF10, SF20, SF25, SF30, and SF60 are respective 1T, 2T, 2.5T, 3T,and 6T. Line-pull roller is suitable for pulling in straightline fashion and turning.
- 3.2 Capacities of SC102 and SC104 are all 1T. They are respectively with two and four steering wheels and suitable for turned pulling.
- 3.3 CM60, CM120 and CM240 are combination, capacities of which are respectively 6T, 12T and 24T. They are suitable for pulling large goods.
- 3.4 ST30, ST60 and ST120 participate of pulling rollers. Their capacities are respectively 3T, 6T and 12T. They can be pulled to change direction.

- 3.5 SK20, SK30 and SK60 participate of chain rollers. Their capacitities are respectively 20T,30T and 60T. They can be pulled to change direction. They should be used on steel plate (thickness ≥10mm).
- 3.6 RC15, RC50 is a pry with a capacity of 1.5T, 5T respectively and it is necessary accessory of above skates.
- 3.7 Three attachments of TR40, TR50 and PC40, PC50 and RS40, RS50 can be combined to use, or be purchased to use separately.
- 3.8 Capacity of SR6 is 6T, rollers of two sides have the function of floating and overturning.
- 3.9 Capacity of SW4 is 4T, packed in iron box and can be combined to use.


### 4. EXPLODED FIGURES & PARTS LISTS

4.1 Exploded figure of SF10 and parts list




No.	Description	Q'ty
1	Frame	1
2	Retaining ring	4
3	Axle	2
4	Washer	12
5	Wheel	4
6	Bushing	4

### 4.2 Exploded figure of SF20 and parts list




No.	Description	Q'ty
1	Frame	1
2	Retaining ring	4
3	Axle	2
4	Washer	8
5	Wheel	8
6	Bushing	2
7	Washer case	8

# 4.3 Exploded figure of SF25 and parts list




No.	Description	Q'ty
1	Frame	1
2	Retaining ring	4
3	Axle	2
4	Washer casing	4
5	Bearing	4
6	Roller	2

4.4 Exploded figure of SF30 and parts list



No.	Description	Q'ty
1	Frame	1
2	Retaining ring	4
3	Axle	2
4	Washer casing	8
5	Bearing	8
6	Roller	4


4.5 Exploded figure of SF60 and parts list 2 to enupil behalox 2 at a



No.	Description	Q'ty
1	Frame	1
2	Retaining ring	6
3	Axle	3
4	Washer	12
5	Bearing	12
6	Roller	6


OF 7 Persining and
Parties clear teaching
gnieso reiteaW   01
(1 Roller

# 4.6 Exploded figure of SC102 and parts list to study behalface at




No.	Description	Q'ty
1	Nut	8
2	Spring washer	8
3	Flush washer	8
4	Wheel	2
5	Screw	8
6	Rubber plate	1
7	Retaining ring	4
8	Axle	2
9	Frame	1
10	Washer casing	4
11	Roller	2

# 4.7 Exploded figure of SC104 and parts list




No.	Description	Q'ty
1	Nut	16
2	Spring washer	16
3	Flush washer	16
4	Wheel	4
5	Screw	16
6	Rubber plate	1
7	Retaining ring	1

# 4.8 Exploded figure of CM60 and parts list a to a world be bold of TA




No.	Description	Q'ty
1	Frame	2
2	Rod	2
3	Washer	16
4	Bearing	16
5	Roller	8
6	Retaining ring	8
7	Axle	4

# 4.9 Exploded figure of CM120 and parts list




No.	Description	Q'ty
1	Frame	2
2	Retaining ring	8
3	Axle 19das V	4
4	Roller	2
5	Washer	24
6	Roller	12
7	Bearing	24

# 4.10 Exploded figure of CM240 and parts list




No.	Description	Q'ty
1	Retaining ring	8
2	Axle	4
3	Rod	2
4	Frame	2
5	Washer	32
6	Roller	16
7	Bearing	32




No.	Description	Q'ty
1	Frame	1
2	Bearing	1
3	Roller bracket	1
4	Retaining ring	1
5	Nut	1
6	Washer	2
7	Bolt	1
8	Welded handle	1
9	Washer	4
10	Retaining ring	4
11	Roller	4
12	Bearing	8
13	Washer casing	4

# 4.12 Exploded figure of ST60 and parts list



No. Description		Q'ty
10	Draw base	1
2	Retaining ring 18	2
3	Long axle	1
4	Weld handle	. 1
5	Pallet rack	1
6	Bearing	2
7	Retaining ring 20	8
8	Axle	4
9	Locknut	6
10	Washer 10	12
11	Screw	4
12	Plate	2
13	Nut	4
14	Left roller bracket	1
15	Retaining ring 50	2
16	Right roller bracket	1
17	Washer casing	16
18	Bearing	16
19	Roller	8

# 4.13 Exploded figure of ST120 and parts list




No.	Description	Q'ty
1	Draw base	_ 1
2	Retaining ring 18	4
3	Long axle	1
4	Weld handle	1
5	Pallet rack	1
6	Bearing	2
7	Retaining ring 20	8
8	Axle	4
9	Screw	4
10	Plate	2
11	Nut	4
12	Washer 10	8
13	Short axle	1
14	Locknut	4
15	Left roller bracket	1


# 4.15 Exploded figure of RC50 and parts list

16	Retaining ring 50	2
17	Right roller bracket	11
18	Washer casing	16
19	Bearing	16
20	Roller	8

### 4.14 Exploded figure of RC15 and parts list




No.	Description	Q'ty
1	Washer	2
2	Roller	2
3	Split pin	2
4	Pry bracket	16




No.	Description	Q'ty
1	Washer	2
2	Roller	2
3	Split pin	2
4	Pry bracket	1

# 4.16 Exploded figure of SK20 and parts list to study beholded at a




No.	Description	Q'ty
1	Frame	2
2	Angle steel	2
3	Rod	2
4	Roller bracket	. 4
5	Bolt	2
6	Turn pallet	2
7	Nut	2
8	Disk	2
9	Axle	2

### 4.17 Exploded figure of SK30 and parts list




No.	Description	Q'ty
1	Frame	2
2	Angle steel	2
3	Rod	2
4	Roller bracket	4
5	Bolt	2
6	Turn pallet	2
7	Nut	2
8	Disk	2
9	Riveted pipe	2


### 4.18 Exploded figure of SK60 and parts list to study beloaded with



No.	Description	Q'ty
1	Frame	2
2	Angle steel	2
3	Rod	2
4	Roller bracket	4
5	Bolt	2
6	Turn pallet	2
7	Nut	2
8	Disk	2
9	Riveted pipe	2


# 4.19 Exploded figure of TR40, PC40, RS40 and parts list






No.	Description	Q'ty
TR40	Base	1
PC40	Turn pallet	1
RS40	Roller bracket	1


# 4.20 Exploded figure of TR50, PC50, RS50 and parts list






No.	Description	Q'ty
TR50	Base	1
PC50	Turn pallet	9 1
RS50	Roller bracket	1

### 4.21 Exploded figure of SR6 and parts list



No.	Description	Q'ty	No.	Description	Q'ty
1	Bearing 8210	1	10	Washer casing	8
2	Pallet rack	1	11	Roller bracket	2
3	Reaining ring 18	4	12	Optic axis	4
4	Major axle	1	13	Reaining ring 20	16
5	Draw base	1	14	Reaining ring 50	1
6	Minor axle	1	15	Base frame	1
7	Weld handle	1	16	Pin axle	4
8	Bearing 80304	8	17	Washer 20	4
9	Roller Ø85×85	4		1100 NEUROI	

# 4.22 Exploded figure of SK04 and parts list in second beholded 15.4



No.	Description	Q'ty	No.	Description	Q'ty
1	Fixed base	2	8	Retaining ring 20	2
2	Upper pull rod	2	9	Hexagon bolt M10×110	2
3	Hexagon nut M6	2	10	Axis of gravity	2
4	Bottom pull rod	2	11	Disk assembly	2
5	Hexagon nut M10	2	12	Hexagon bolt M6×45	2
6	Base	2	13	Iron box	1
7	Steel ball SØ11	44	14		